

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety ming maintenance activiti		Great and the state of the sta			
Date of Maintenance:	0//	for Maintenance:	0 /	2		
Property Address: 67				ame: Bed Uss	C-	
Municipality: 4	ZIP:		ntification Number:			
Maintenance Permit N	P692314133 M			lie's Sewer Service/L2	<u></u> 2428	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? Yes Yes from a sep	tic, holding, pret			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	□ Yes 🕅 (lo	☐ Yes No	☐ Yes 【No		
	Septic/Holding Tank #2	☐ Yes ⊠No	☐ Yes No	☐ Yes ☑ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes X No	☐ Yes 风No	☐ Yes No		
	of septage were removed					
Tank #1 1052	gal Tank #2 /250	gal Pretreatmen	t tankg	al Pump Tank 30	gal	
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or othe	r concerns.	
	e					
6. Location of septage	disposal:					