

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit m	nust be completed	
<u>prior</u> to perfo	rming maintenance activit	ies and remain op	-site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance:	Reason	for Maintenance:	Ken I	ary		
Property Address: 2	2770 Imperi	a Ave M	Property Owner's N	ame: Dennis	Bath	
Municipality: Fore	+ LK ZIP: 55	72 Property Ide	ntification Number:			
+	14X/X 77UZ					
Maintenance Permit N	10: <u>11 1000257 45</u>	waintainer Name ar	id License No. Smi	lie's Sewer Service/L2	2428	
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements) = % Slu			% Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers se3. Is there evidence	nove septage: Maintenal curely replaced? Yes of tank leakage from a sep aged, cracked, or structure	□ No otic, holding, pretr	eatment or pump	tank below the opera	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes [No	☐ Yes ☐No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes 🖁 No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes No	☐ Yes ⊅No	☐ Yes ☐ No		
Tank #1 1500	of septage were removed gal Tank #2 //// : List any troubleshooting	gal Pretreatmen		al Pump Tank 300	gal r concerns.	
-		<i>(</i>	1	1 11		
6. Location of septage	e disposal: Was	7 (0	land	HAP	5	
				//~ /	ECC.	