

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

					the second secon	
This section must be	oe completed in its entiret	y to constitute a v	alid maintenance ¡	permit. This permit	must be complete	
<u>prior</u> to peri	forming maintenance activ	rities and remain o	n-site for the dura	tion of the maintena	ance activity.	
Date of Maintenance	e: 10-3-23 Reason	on for Maintenance:	Rutiu			
Property Address:	6188 53 rd S	st So	Property Owner's I	Name: Kick F	Sraun	
Municipality: 4	ton zip: 55	Property Ide	entification Number	r:		
Maintenance Permit	No 04353 y 37029	Maintainer Name a	nd License No. Pin	kv's Environmental Se	ewer Service / I 167	
				y =	Wel Service/ E10/	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (i	f no provide measurements	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Mainten	ance Hole Other (3	
	ecurely replaced? Yes			Deep		
	of tank leakage from a se		roatmont or num-	tool by the		
evidence of dam	naged, cracked, or structu	rally unsound main	tenance halo cove	tank below the ope	rating depth or	
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank ————————————————————————————————————	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pump Tank	Yes No	Yes No	☐ Yes ☐No		
4. How many gallons	of septage were removed	1?				
Tank #1 1250	gal Tank #2	gal Pretreatment	tank g	al Dump Tank	and I	
. Other information	: List any troubleshooting	minor repairs cor	ducted tank safe	ty consorre an all	gal	
	nothing	, milor repuirs cor	iducted, talik sale	ty concerns, or othe	r concerns.	
. Location of septage	e disposal: www.	etment Pl	nt St. Parl			
Pinky's Environmental Sewer Service Inc.						
		PO Box 35	4			
Afton MN 55001						

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673