

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to prior to performing maintenance activities		
Date of Maintenance: 10-10-23 Reason for	or Maintenance: Cuttu	
Property Address: 155 Rustic Dry		s Name: Sterce Dione Kisch
Municipality: Muntanali ZIP: 5511	S Property Identification Numb	per:
Maintenance Permit No: 2759903913Ma		
Maintenance Permit No: 2191938116 Ma	aintainer Name and License No. P	inky's Environmental sewer service/ £16/3
Maintenance Performed	Tank Measurement (must	be completed if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Tank ———	in
Sludge and scum measured	Sludge Level in Tank ———	in Scum Level in Tank in
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100	
\square Yes \square No (if no provide measurements)	= % Sludge & Scum	Tanks must be pumped if 25% or greater
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural 	cic, holding, pretreatment or pur	
Tank	Leaking Out Leaking In	Cover Damage
Septic/Holding Tank #1	☐ Yes ☐ No ☐ Yes ☐ No	Yes No
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	Yes No
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	Yes No
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	o □ Yes □ No
4. How many gallons of septage were removed?		gal Dump Tank
Tank #1 SDD gal Tank #2 5. Other information: List any troubleshooting,		
/		
6. Location of septage disposal:	+ + 101.+	+01

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673