## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

The section mase	be completed in its entire	ty to constitute a v	alid maintenance p	permit. This permit r	must be complet	
<u>prior</u> to per	forming maintenance activ	rities and remain or	n-site for the dura	tion of the maintenar	nce activity	
Date of Maintenanc	e: <u>/0-20-23</u> Reaso	on for Maintenance:	Poutus		rec detivity.	
Property Address:	1700	TYL No		Vamo: Doug P	VC   110	
Municipality: St	Mwater zip:55	000	roperty owner si	valle.	your	
marricipatity. Ott	202/10 1020	Property Ide	entification Number	:		
Maintenance Permit	No.C2340c132052	Maintainer Name a	nd License No. Pinl	ky's Environmental Se	wer Service/ L16	
	nance Performed					
			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank ———— in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
arragined of daily	naged, cracked, or structu ———————————————————————————————————	Leaking Out	Leaking In	Yes No Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	Yes No			
				Yes No		
	Septic/Holding Tank #2	☐ Yes ☐No	Yes Yo	☐ Yes ☐ No ☐ Yes ☐ No		
	Septic/Holding Tank #2  Pretreatment Tank	☐ Yes ☐ No				
		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
. How many gallons	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank  Pump Tank  s of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 <u>760</u> . Other information	Pretreatment Tank  Pump Tank  s of septage were removed  gal Tank #2	Yes No Yes No ? gal Pretreatment , minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Pump Tank	Concorns	
Tank #1 <u>760</u> . Other information	Pretreatment Tank  Pump Tank  s of septage were removed  gal Tank #2	Yes No Yes No ? gal Pretreatment , minor repairs con	Yes No Yes No Yes No tank ga	Yes No Yes No Yes No Pump Tank	concorns	
Tank #1 <u>760</u> Other information  System	Pretreatment Tank  Pump Tank  s of septage were removed  gal Tank #2	Yes No Yes No Yes No Repairs con Makes	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankga  iducted, tank safet	Yes No Yes No Yes No Pump Tank ty concerns, or other	concerns.	
Tank #1 <u>760</u> Other information  System	Pretreatment Tank  Pump Tank  s of septage were removed  gal Tank #2	Yes No Yes No Yes No Repairs con Makes	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankga  iducted, tank safet	Yes No Yes No Yes No Pump Tank ty concerns, or other	concerns.	
Tank #1 <u>760</u> Other information  System	Pretreatment Tank  Pump Tank  s of septage were removed  gal Tank #2	Yes No Yes No Yes No Repairs con Makes	Yes No Yes No Yes No tank ganducted, tank safet	Yes No Yes No Yes No Pump Tank ty concerns, or other	concerns.	

PO Box 354

Afton MN 55001