## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must h	e completed in its optimate	t			No. Committee of the Co
prior to perf	e completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed
Date of Mainten	orming maintenance activit	ies and remain o	n-site for the dura	ation of the maintena	ance activity.
	: 11-29-23 Reason	for Maintenance:	Keutiu		
Property Address: 2	218 Boom (	<u>ld</u>	Property Owner's	Name: Plyssc	Tuttle
Municipality: Sh		87 Property Id	entification Numbe	r:	
Maintenance Permit	No: j9994m3299BA	Maintainer Name :	and License No. Din	lo de Emilia de 1.6	
		Tame t	and License No. Pill	ky s Environmental Se	ewer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Soum Level in Tank			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
I. Access used to re	move septage:   Maintenan			s mase se pamped	11 25% Of greater
	ecurely replaced? Yes		enter authorization c	ode)	
evidence of dam	of tank leakage from a sept aged, cracked, or structura	lly unsound mair	reatment or pump	tank below the oper	ating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers?  Yes Yes					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ≦No	☐ Yes ☐ No	
	Septic/Holding Tank #2	Yes No	☐ Yes →No	☐ Yes 🚽 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons	of septage were removed?				
Tank #1 750	_gal Tank #2 750	gal Pretreatment	tank ga	al Pump Tank	1
Other information	List any troubleshooting, r	ninor repairs cor	nducted, tank safet	ty concerns or other	gal
Tone		•	and sure	ty concerns, or other	concerns.
Location of septage	disposal: _way -	TP			
	Pinky's	Environmental Se	wer Service Inc.		
		PO Box 35			
		Afton MN 55	001		

Maintenance activities must be reported to the Department within 90 days.

P: 651-439-4847 License Number: L1673