Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	pe completed in its entire	ty to constitute a v	alid maintenance	permit This permit		
prior to perf	forming maintenance activ	rities and remain o	n-site for the dura	tion of the maintena	must be completed	
Date of Maintenance	e: <u>//-27-23</u> Reaso	on for Maintenance:	Keirtine		nee activity.	
Property Address: 1	2335 241 5	t No	Property Owner's	Name: Tam Ka	Trnector	
Municipality: (C)	e Flmo zip:55	CMZ Property Id	entification Numbe	r:	z megor	
Maintenance Permit	No: LO327m32642	Maintainer Name a	and License No. Pin	ky's Environmental Co		
				ky 3 Environmentat se	wer service/ L16/3	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		s) = % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Mainten	ance Hole Other			11 25% of greater	
	ecurely replaced? Yes		enter authorization c	ode)		
evidence of dam	of tank leakage from a se naged, cracked, or structu	rally unsound mair	reatment or pump	tank below the oper	ating depth or	
		arry unsound mail	teriance note cove	ers? Yes No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	of septage were removed					
Tank #1 <u>/500</u>	gal Tank #2 /000	_gal Pretreatment	tankg	al Pump Tank	gal	
. Other information	: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other	Concerns	
None				, server, or other	concerns.	
		e e				
. Location of septage	e disposal: wwt					
				101 To 10		
	Pinky'	s Environmental Se	wer Service Inc			
		PO Box 35				
		Afton MN 55				

Maintenance activities must be reported to the Department within 90 days.