

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

No. 10 Aug. 10	ompleted in its entirety t	o constitute a van	a maintenance pe	rmit. This permit mu	
<u>prior</u> to perforr	ning maintenance activiti	es and remain on-	site for the duration	on of the maintenance	e activity.
Date of Maintenance: _		for Maintenance:		Mainte	nance
Property Address: <u>88</u>	83 Jane Ro	A M	roperty Owner's Na	ame: Patrick	McHIL
	e Elmo ZIP: 550				_
Maintenance Permit No	:4337844057 M	laintainer Name an	d License No. Ron's	s Sewer Service/ L210	3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? (Yes of tank leakage from a sepaged, cracked, or structur	tic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or
	Tank	<b>Leaking Out</b>	Leaking In	<b>Cover Damage</b>	
	Septic/Holding Tank #1	☐ Yes ♣ No	☐ Yes ☐No	☐ Yes ☐ No	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No		
		_		☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	
Tank #1 1250	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Regal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankg	Yes No Yes No Yes No Yes No Yes No	gal
Tank #1 1250	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No Yes No Yes No Yes No Regal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankg	Yes No Yes No Yes No Yes No Yes No	gal er concerns.
Tank #1 1250	Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were removed  gal Tank #2  : List any troubleshooting	Yes No Yes No Yes No Yes No Resident No Re	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankg nducted, tank safe	Yes No Yes No Yes No Yes No Yes No	er concerns.