Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section mus	t be completed in its			- Joseffi Mairitei		
prior to be	t be completed in its entiret	y to constitute a v	alid maintenance	permit. This permit	must be completed	
	erforming maintenance activ	ities and remain o	n-site for the dura	ation of the maintena	ance activity.	
Date of Maintenan	nce: <u>//- 8 - 23</u> Reaso	n for Maintenance:	Recition	٤		
Property Address:	13704 301 8	St Cr No	Property Owner's	Name: Bau	Kreicher	
Municipality:	Mwater zip:550	282 Property Ide	entification Number	or.		
Maintenance Perm	nit NoCICE210323041	Maintein		1		
	nit NoQ0521q323041	Maintainer Name a	ind License No. Pin	iky's Environmental Se	ewer Service/ L1673	
Maint	enance Performed	Tank Mea	surement (must b	e completed if tanks	NOT numped)	
Tank(s) Pumped		the state of the s	Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
. Access used to	remove septage: Maintena				11 25% Of greater	
. Is there evidend evidence of da	ce of tank leakage from a sep amaged, cracked, or structur	otic, holding, preti ally unsound main	reatment or pump tenance hole cove	tank below the operers? Yes	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ➡No	☐ Yes → No	☐ Yes ⊋No		
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	Yes No	Yes No		
	Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
How many gallor	_					
Jane	ns of septage were removed?	?				
Tank #1 /50	os of septage were removed? gal Tank #2	gal Pretreatment	tank g	al Pump Tank	and .	
Tank #1 /50	gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal	
Tank #1 / Society Other information	gal Tank #2 on: List any troubleshooting,	gal Pretreatment	ducted, tank safe	ty concerns or other	Concorns	
Tank #1 / Society Other information	gal Tank #2	gal Pretreatment	ducted, tank safe	ty concerns, or other	concerns.	
Other information	gal Tank #2on: List any troubleshooting,	gal Pretreatment minor repairs con	ducted, tank safe	ty concerns, or other	concerns.	
Other information	gal Tank #2 on: List any troubleshooting,	gal Pretreatment minor repairs con	ducted, tank safe	ty concerns, or other	concerns.	
Other information	gal Tank #2	gal Pretreatment minor repairs con	ducted, tank safe	ty concerns, or other	concerns.	
Tank #1 /500. Other information	gal Tank #2	gal Pretreatment minor repairs con	ducted, tank safe	ty concerns, or other	concerns.	

PO Box 354

Afton MN 55001