Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	on completed in its anti-					
prior to perf	oe completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be completed	
prior to peri	orning maintenance activ	rities and remain o	n-site for the dura	ation of the maintena	ance activity.	
Date of Maintenance	e: 1/-7-23 Reason	on for Maintenance:	Keuthue			
Property Address:	6-110 upper	22nel Sts	Property Owner's	Name:	tellten	
Municipality:	Merel ZIP:58	Property Id	entification Number	r.		
Maintenance Permit	No. 445121320036	Haintai N	enemedelon Humbe	1.		
	No: <u>44512v32636</u>	Maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Fank (s) Pumped		Liquid Level of Tank — in			
$\ \square$ Sludge and scum		II	Sludge Level in Tank in Scum Level in Tank in			
	Do tanks need to be pumped? Sludge + Scum					
☐ Yes ☐ No (i	f no provide measurements	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Mainten	ance Hole Sother	ontor authorization		11 23% of greater	
	ecurely replaced? Yes		enter authorization c	ode)		
3. Is there evidence	of tank leakage from a se	Dtic holding prot	roatment			
evidence of dam	aged, cracked, or structu	rally unsound main	tenance hale cover	tank below the oper	rating depth or	
			Total Cove	ers: Les No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
. How many gallons	of septage were removed	?				
Tank #1 / 500	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	aal	
. Other information	: List any troubleshooting	minor repairs con	ducted tank safet	h		
Mare	- too old of	or Manha	le	-,, 51 511161	concerns.	
· Lucation of Septage	1 () . \ -					
	disposal: Ww T	P				
					,	
		s Environmental Se	wer Service Inc.			

Afton MN 55001