## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must b	o completed in the control	4 2			Section of the Control of the Contro	
prior to port	e completed in its entirety	to constitute a v	alid maintenance p	permit. This permit	must be completed	
prior to peri	orming maintenance activit	ies and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	:: 12-25-23 Reason	for Maintenance:	Recitus	2		
Property Address: 4		0	Property Owner's 1	Name: Dunie	Heffrin	
Municipality:	ton zip:550	1	entification Number			
Maintenance Permit	No:18370032453					
/		Tame a	The Electise No. Fill	ky s Environmental Se	ewer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (i	f no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintenan	So Hala Dubani			11 25% of greater	
			enter authorization c	ode)		
	ecurely replaced? Yes					
a. is there evidence	of tank leakage from a sept	tic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?					
Tank #1 15 0	gal Tank #2	gal Pretreatment	tank ga	J. Dump Tank		
. Other information	: List any troubleshooting,	minor repairs con	dusted tank safet	rump rank	gal	
	h S	thing	ducted, tank sare	ty concerns, or other	concerns.	
	110					
. Location of septage	e disposal:w	Treatmen	tp/ints	T. Pul		
	Pinky's	Environmental Se	wer Service Inc			
			Total IIIC.			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673