

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a v	alid maintenance p	ermit. This permit	must be completed
<u>prior</u> to perfo	orming maintenance activit	ies and remain o	n-site for the durat	ion of the maintena	ince activity.
Date of Maintenance	: 9/15/16 Reason	for Maintenance:	Forter		
Property Address:	9036 COLL St. 1	<u> </u>	Property Owner's N	lame: Coming 1	Velson
Municipality: 54.	1/2 for ZIP: 550	\$2 Property Ide	entification Number	:	
	No: <u>Q 7065 i 4114</u> N				2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
\square Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers se Is there evidence 	move septage: Maintenan ecurely replaced? Yes C of tank leakage from a sept aged, cracked, or structura	□ No tic, holding, pret	reatment or pump	tank below the one	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes 🗹 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
How many gallons	of septage were removed?				
Tank #1/650	gal Tank #2 /000	gal Pretreatment	tank ga	al Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs coi	nducted, tank safe	ty concerns, or othe	er concerns.
-					