

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
prior to perforn	ning maintenance activitie	s and remain on-s	site for the duration	on of the maintenanc	e activity.
Date of Maintenance:	9/12/16 Reason fo	// )			)
Property Address: 452	3 Tenslewood	Ln Pr	operty Owner's Na	ime: Stan Vo	se/
Municipality: 5+ 6	ZIP:	Property Iden	tification Number:		
138 2	1012			ie's Sewer Service/L2	
Maintenance Permit No	: Stalles 37/9 Ma	aintainer Name and	a License No	le 3 Sewer Service/LZ	. 420
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: X Maintenan	ce Hole $\Box$ Other (e	nter authorization co	ode)	
2. Were all covers sec	curely replaced? Yes	□No			
3. Is there evidence of	of tank leakage from a sept ged, cracked, or structura	tic, holding, pretr	eatment or pump tenance hole cove	tank below the oper ers?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	!			
Tank #1/250 gal Tank #2				al Pump Tank	gal
- 0.1	· List any troubleshooting	minor repairs ço	nducted, tank safe	ety concerns, or othe	er concerns.
Dotat	Soffle pred	15 to Se	2 replace		