Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

				THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	Name and Address of the Owner, where the Owner, which is the O	
This section must be	e completed in its entirety	to constitute a va	alid maintenance p	ermit. This permit	must be completed	
prior to perfo	orming maintenance activi	ties and remain or	n-site for the durat	ion of the maintena	nce activity.	
Date of Maintenance:	12 11 82	n for Maintenance:				
Property Address:		1.0		ame:TIMe S	herie (th	
Municipality: CIK	LEIME ZIP: SS				100000	
Maintenance Permit N						
maintenance Perinit I	No:5873343305	maintainer Name a	nd License No. Pink	y's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	move septage: Maintena	nce Hole Other (e	enter authorization co	de)		
	ecurely replaced? Yes					
	of tank leakage from a se		reatment or numb	tank bolow the one	rating double as	
evidence of dama	aged, cracked, or structur	ally unsound main	tenance hole cover	rs? Yes No	ating depth or	
	Tank					
	The state of the s	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed	?				
	gal Tank #2 /D DD				gal	
. Other information	: List any troubleshooting	minor repairs cor	nducted, tank safet	y concerns, or othe	er concerns.	
	No	Chiny				
			······································			
. Location of septage	e disposal:	trestmen	EPINTSLA	ful f		
	Pinky'	s Environmental Se	wer Service Inc.			
	,	PO Box 35				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673