Washington 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730 Subsurface Sewage Treatment System Maintenance P

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

				,	.aee i ei iiiie
This section must be	completed in its entirety	to constitute a va	alid maintenance p	ermit. This permit	must be completed
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance:	11 // 17	for Maintenance:		and the manifelia	mee detivity.
O1	RedSOIT		1000		
Property Address:	100 55° S	MO	Property Owner's N	lame: Stan	ECUYO
Municipality:	LEIMO ZIP:556	Property Ide	ntification Number	:	
Maintenance Permit N	0:h4557h33038M	Maintainer Name a	nd License No. Pink	y's Environmental Se	ower Service / 11672
				y = 2.17 ii offinientat 50	Wel Service/ E10/3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenan	oce Hole Other (c			3
			enter authorization co	ode)	
2. Were all covers securely replaced? Yes No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of dama	or tank leakage from a sept	tic, holding, pretr	eatment or pump	tank below the ope	rating depth or
evidence of damaged, cracked, or structurally unsound maintenance hole covers? \square Yes \square No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons o	of septage were removed?				
Tank #1 1500 gal Tank #2/000 gal Pretreatment tankgal Pump Tank gal					
. Other information:	List any troubleshooting,	minor repairs con	ducted, tank safet	v concerns, or othe	r concerns
	nothir		1.5	,	· concerns.
			1	1	
. Location of septage	disposal:wwt	certmenty	Plant St. Pm		
	Diplovia	Environmental C	· · · · · · · · · · · · · · · · · · ·		
	FIIIKY S	Environmental Se			
PO Box 354					

P: 651-439-4847 License Number: L1673

Afton MN 55001