## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section mus	t be seemed to the terminal				anioc i ci illic	
prior to p	st be completed in its entire	ety to constitute a v	alid maintenance	permit. This permit	nust be completed	
	indifferentiance acti	vities and remain o	n-site for the dur	ation of the maintena	nce activity.	
Date of Maintenar	nce: 12-6-23 Reas	on for Maintenance:	Rath	e		
Property Address:	80 Quanwell	Arc So	Property Owner's	Name: Gam	Rooal	
Municipality:	Kelenel ZIP: S	Property Id	entification Number			
Maintenance Perm	nit No: +1901m3245	7.Maintainea N	enemeation rambe			
	nit No: <u> </u>	Maintainer Name a	and License No. Pir	nky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured			Sludge Level in Tank in Sound in			
Do tanks need to be pumped?			Sludge + Scum - / 1:			
☐ Yes ☐ No (if no provide measurements)						
1. Access used to	remove sentago:		= % Sludge & Scum Tanks must be pumped if 25% or greater  Hole Other (enter authorization code)			
2 Word all sources	mainter	Tance Hole Gother (	enter authorization o	code)		
2. Were all covers	s securely replaced? Yes	i ∐ No				
3. Is there eviden	ce of tank leakage from a se	eptic, holding, pret	reatment or pump	tank below the oper:	ating donth or	
evidence of da	amaged, cracked, or structu	rally unsound mair	tenance hole cov	ers? Yes No	iting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	Yes No	Yes No	☐ Yes ☐ No		
4. How many gallo	ns of septage were removed	1?				
Tank #1 <u>125</u>	gal Tank #2 / LDD	gal Pretreatment	tank g	al Pump Tank		
. Other information	on: List any troubleshooting	, minor repairs cor	ducted tank safe	ty concerns	gal	
	nxt	Lin	idacted, talk sale	ty concerns, or other	concerns.	
	1 10		1			
. Location of septa	age disposal: w	Wheato	ent Plat	St. Parl		
	Pinkv	's Environmental Se	wor Conjigo Inc			
	· ·····y	PO Box 354				
		Afton MN 550				

Maintenance activities must be reported to the Department within 90 days.