

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
<u>prior</u> to perfor	ning maintenance activition	es and remain on-	site for the duration	on of the maintenanc	ce activity.
Date of Maintenance:	9/8/16_ Reason f	or Maintenance: _	Rostine		
Property Address: 2		1	roperty Owner's Na		Nollin
Municipality: Juest	Lake ZIP:	Property Ider	tification Number:		
Maintenance Permit No	0: <u>44608h 41.34</u> M	aintainer Name an	d License No. Smil	ie's Sewer Service/L2	.428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see	nove septage: Maintenan curely replaced? Yes [ of tank leakage from a sep	□No			ating depth or
evidence of dama	ged, cracked, or structura	ally unsound main	tenance hole cove	rs?	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes 💢 No	☐ Yes ☒ No	
	Septic/Holding Tank #2	☐ Yes →No	☐ Yes ⊠No	☐ Yes 🔀No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank					gal
	List any troubleshooting,				
					-
6. Location of septage					