

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to					
prior to perform	ming maintenance activitie	s and remain on-	site for the duration	on of the maintenanc	e activity.	
Date of Maintenance:	9-9-16 Reason to	or Maintenance: _	Rea M	a. 5/		
/	2=0 11/1			me: Dana	Hallber	
Property Address: / []	059 N Shor	PI PI	roperty Owner's Na	me: Juny	11 41 12010	
Municipality:	A LK ZIP: 550	roperty Iden	tification Number:		_	
Maintenance Permit No	5:08350c413 Ma	aintainer Name an	d License No. Smil	ie's Sewer Service/L2	428	
	<u> </u>					
Maintenar	Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if I	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
3. Is there evidence	curely replaced?	tic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☑No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes [] No	☐ Yes ☐ No	☐ Yes No		
Tank #1 1500	of septage were removed? gal Tank #2 /// / : List any troubleshooting,	gal · Pretreatmen	t tankg nducted, tank safe	al Pump Tank 30 ety concerns, or othe	gal gal er concerns.	
6	, 1					
6. Location of septag	e disposal: \was l	2 Cc	Lan	A App	0/4	
				U V	/	