

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	be completed in its entiret forming maintenance activ					
	e: 9-12-23 Reason			Routine		
Property Address:	11599 Leewar	d Ave. S.	Ave. S. Property Owner's Name: Bill Berg			
	tage Grove ZIP: 55				J	
	: No: m1612a34539				5	
Maintenance Performed		Tank Me	Tank Measurement (must be completed if tanks NOT pumped)			
✓ Tank(s) Pumped			Liquid Level of Tankin			
Sludge and scum			Sludge Level in Tankin Scum Level in Tankin Sludge + Scum/ Liquid LevelX 100			
tanks need to b			= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)				
	emove septage: Maintena		(enter authorization co	ode)		
	securely replaced? 🗹 Yes			tank holow the oper	ating donth or	
	e of tank leakage from a se naged, cracked, or structu				ating depth of	
	Ta nk	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	□Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank Pump Tank	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No		
4. How many gallor	Pump Tank	☐ Yes ☐ No				
, ,		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 \000	Pump Tank ns of septage were removed	☐ Yes ☐ No d?gal Pretreatme	☐ Yes ☐ No nt tankg	Yes No		
Tank #1 \000	Pump Tank ns of septage were removed gal Tank #2	☐ Yes ☐ No d?gal Pretreatme	☐ Yes ☐ No nt tankg	Yes No		
Tank #1 \000	Pump Tank ns of septage were removed gal Tank #2 on: List any troubleshooting	☐ Yes ☐ No d?gal Pretreatme	☐ Yes ☐ No nt tankg	Yes No		
Tank #1 \00 0 5. Other information	Pump Tank ns of septage were removed gal Tank #2 on: List any troubleshooting	Yes No d?gal Pretreatme g, minor repairs co	Yes No nt tankga onducted, tank safe	Yes No		
Tank #1 \00 0 5. Other information	Pump Tank ns of septage were removed gal Tank #2 on: List any troubleshooting	Yes No d?gal Pretreatme g, minor repairs c Apply Meyer Sewer 5325 Mannir	Yes No nt tank ga onducted, tank safe Service ng Ave S	Yes No		
Tank #1 \00 0 5. Other information	Pump Tank as of septage were removed gal Tank #2 on: List any troubleshooting ge disposal:	Yes No No Yes No No Pretreatments of the second of the	Yes No nt tank ga onducted, tank safe Service ng Ave S	Yes No		

White Copy-Maintainer submits to Washington County / Yellow Copy-Property Owner Record

Maintenance activities must be reported to the Department within 90 days.



Minnesota Pollution Control Agency Signature Form

Property Address: 11599 LEEWard AUE. S	
Property Address: 11599 LEEWard AUE. S City: Hastings / Cottage Grove State MW	Zip Code: 55016
If the owner refuses to allow a Subsurface Treatment System (SSTS hole, have them complete and sign the following statement.) to be pumped through the maintenance
I, Bill Beng, refuse to liquids through the maintenance hole. I understand that the removal points is not considered a compliant method of solids removal and derequirements of Minn. R. 7080.2450 and 7082.0600.	
Sign here and return:	
Owner's Name: Bill Berg	
X Signature: Bull Bug	9
Date: 9/15/23	