

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	be completed in its entire		_			
Date of Maintenan	ce: 10-21-23 Reas	on for Maintenance:	:	Emerge	ncv	
Property Address:	14616 Afton B	IVA S	Property Owner's N			
The state of the s	Afton ZIP: 97					
	it No: W 2 555 K 3460 S					
		- Manneamer Hame	and Ereemse no. <u>inte</u> ye			
Maintenance Performed		Tank Me	Tank Measurement (must be completed if tanks NOT pumped)			
 ✓ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Sludge Level in Sludge + Scum = % Sludge & S	Liquid Level of Tankin Sludge Level in Tankin Scum Level in Tankin Sludge + Scum/ Liquid LevelX 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers 3. Is there evidend	remove septage: Mainte securely replaced? Yes ce of tank leakage from a s amaged, cracked, or struct	s □ No eptic, holding, pre	treatment or pump	tank below the oper	rating depth or	
	Ta	Leaking Out	Leaking In	Cover Damage		
	Ta nk	Leaking Out	Leaking In	Cover Damage		
	Ta					
	Ta nk	Leaking Out	Leaking In	Cover Damage		
	Ta nk Septic/Holding Tank #1	Leaking Out ☐Yes ☐ No	Leaking In	Cover Damage		
	Ta nk Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No		
4. How many gallo Tank #1	Ta nk Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank ons of septage were remove gal Tank #2 Tank #2 150 ion: List any troubleshooting	Leaking Out Yes No Yes No Yes No Yes No Yes No gal Pretreatme	Leaking In Yes No Yes No Yes No Yes No Yes No Ant tank goonducted, tank safe	Cover Damage Yes No Yes No Yes No Yes No Yes No	gal er concerns.	

Maintenance activities must be reported to the Department within 90 days.