

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	site for the durati	on of the maintenar	nce activity.
Date of Maintenance:	4/22/16 Reason	for Maintenance:	Rostine		
-	135 Pentilal	C+S F	roperty Owner's Na	me: Simos	Wirth
Municipality:	127	Property Ide	ntification Number:		· · · · · · · · · · · · · · · · · · ·
Maintenance Permit No	o: <u>y6521j0665</u> M	aintainer Name ar	d License No.	leger 91	15
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? MY Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⋈ No	☐ Yes 🗷 Yo	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 / \ O O gal Tank #2		gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					