

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	id maintenance pe	ermit. This permit r	nust be completed
<u>prior</u> to perfor	ming maintenance activit	<mark>ies and</mark> remain on	-site for the durati	ion of the maintenar	nce activity.
Date of Maintenance:	4/26/16 Reason	for Maintenance:	Rootine		
Property Address:			roperty Owner's N		togerald)
Municipality:	IP: 550	<b>82</b> Property Ide	ntification Number:		
Maintenance Permit No	:n605390667 M	Naintainer Name ar	nd License No	Nexer 9	15
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sec</li><li>3. Is there evidence of</li></ul>	nove septage: Amaintena curely replaced? A Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, preto	eatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes 🌠 No	☐ Yes 🗓 No	
	Septic/Holding Tank #2	☐ Yes <b>∭</b> No	☐ Yes 🎾 No	☐ Yes 🗖 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1500	gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.
-					