

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	iust be completed	
ming maintenance activit	ties and remain on	-site for the durati	on of the maintenan	ce activity.	
4/28/16 Reason	for Maintenance:	ROUTINE			
787 GREYCL	OUD ISDE	S Property Owner's Na	ame: MIKE GA	LADIS_	
CLOUD TWSTIP: 55	7/ Property Ider	ntification Number:			
o: j2596g 0586	Maintainer Name ar	nd License No. M	EYER-019	15	
nce Performed					
	Liquid Level of Tank in				
ieasured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
pe pumped?		Sludge + Scum / Liquid Level X 100			
no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
of tank leakage from a se	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the oper	ating depth or	
ged, cracked, or structul		www.waranananananananananananananananananana			
Tank	Leaking Out	Leaking In	Cover Damage		
		www.waranananananananananananananananananana			
Tank	Leaking Out	Leaking In	Cover Damage		
Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes KNo	Cover Damage Yes 4No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out ☐ Yes ☑ No ☐ Yes ☐ No	Leaking In ☐ Yes	Cover Damage Yes Ano Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes ANO Yes No Yes No Yes No Pump Tank	⊘ gal	
	ming maintenance activity 4/28/16 Reason 787 GREYCL CLOUD TWSPIP: 55 0: j2596g 0586 Dece Performed Dece Performed Dece pumped? Dece powed measurements of provide measurements of tank leakage from a second provide measurement of tank leaka	ming maintenance activities and remain on the season for Maintenance: 187 GREYCLOUD ISDER 187 GREYCLOUD ISDER 187 GREYCLOUD ISDER 187 GREYCLOUD ISDER 188 GREYCLOUD ISDER 189 GREYCLOUD ISDER 180 GREYCLOUD ISOUND ISDER 180 GREYCLOUD ISDER 180 GREYCLOUD ISDER 180 GREY	ming maintenance activities and remain on-site for the duration of the duratio	ming maintenance activities and remain on-site for the duration of the maintenance. 4/38/16 Reason for Maintenance: ROUTINE 1/38/16 ROUTINE 1/38/16 REason for Maintenance: ROUTINE 1/38/16 ROUTINE	