

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	ermit. This permit n	nust be completed
<u>prior</u> to perfor	ming maintenance activitie	es and remain on	site for the durati	on of the maintenar	nce activity.
Date of Maintenance:	4/11/16 Reason f	or Maintenance: _	ROUTI	NE	
Property Address: 3	331 KRAFT CIR	CLE N P	roperty Owner's Na	ame: FRANK T	RICHIE
Municipality: LAKE	ELMO ZIP: 550	<u> </u>	tification Number:		
Maintenance Permit No	D: <u>K3888q.0575</u> M	aintainer Name an	d License No. Me	EYER -L91	5
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? A Yes of tank leakage from a septaged, cracked, or structura	ic, holding, pretr Ily unsound main	eatment or pump tenance hole cove Leaking In	tank below the opers?  Cover Damage	rating depth or
	Tank	Leaking Out			
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ੴNo	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 gal Tank #2		gal Pretreatmen	tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.