

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety t	o constitute a val	id maintenance pe	rmit. This permit i	nust be completed
<u>prior</u> to perform	ming maintenance activitie	es and remain on-	site for the duration	on of the maintena	nce activity.
Date of Maintenance: 4/4/96 Reason for Maintenance: Routine					
Property Address: 2398 Stage coach Jr. M. Property Owner's Name: Jahn Mc Pherson					
Municipality: Nest Lakeland ZIP: 55082 Property Identification Number:					
Maintenance Permit No: K9663z Ø574 Maintainer Name and License No. Meyer - L195					
Maintenan	ice Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
▼ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if n	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole □ Other (enter authorization code) 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ☒ No	☐ Yes ≅No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes ☒No	☐ Yes ⋈ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	•
	of septage were removed?				
Tank #1 /500	gal Tank #2 1000	gal Pretreatmen	t tank ga	al Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					