

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

	System	Location		
Address 15640 Oakhill Rd		Telephone Number		
City Scandia	State MN	ZIP 55074	Property ID N	o./GEO Code
Owner Chris Hanson	Pumping Da	ate Jul 7, 2014		
Contractor				
Maintainer Row Sewer Service	MPCA Licens	se No. L3309	Telephor	ne Number (651) 465-5505
What was done to the system?			Report Liquid	Capacity in Gallons
▼ Tank(s) Pumped		Tank 1: 1,350	Pumpe	d Tank 2: 500 Pumped
Sludge and scum measured.		Tank 3:	Pumpe	d Tank 4: Pumped
Do tanks need to be pumped?		-	Dumpadı 1 a s	
Yes No (If no provide measurements be	elow)	Total Gallons	Pumped: 1,850	)
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.				
				RECEIVED
				SEP 1 9-2016
				PUBLIC HEALTH
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped				
Tank Length in. X Tank Width in. X Tank Depth in. = Tank Volume (cubic inches)				
Tank Radius in. <b>X</b> Tank Radius in. <b>X</b> 3.14 = Tank Volume (cubic inches)				
Tank Volume (cu. in.) / 231.01 = Liquid Capacity Gallons / Tank Depth in. = Gallons/Inch				
Sludge Level in. <b>X</b> Gallons Per Inch	= Sludge	Volume	Gallons	
Scum Level in. <b>X</b> Gallons Per Inch	= Scum \	/olume	Gallons	
Sludge Volume + Scum Volume	= Total S	 ludge and Scum V	olume	Gallons
Total Sludge and Scum Volume / Liq	— Juid Capacity	= Pe	rcent Sludge and	d Scum in Tank %
Scum Layer  Effluent  Sludge Layer	fr	ank Depth measur om invert of outle ipe to bottom of t	followir  1. The to  12 inch  red baffle; c  2. Total	sludge and scum volume is greater percent of the tank's liquid
Signature Will	Dat	e	Sep 13, 2016	Reset Form