

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

	filling maintenance activit			ion of the maintenar	ice activity.
Date of Maintenance:	5/3/2024 Reason	for Maintenance:	2.69		
Property Address:	1835 Parrigh	K9N F	Property Owner's N	lame: Bruce	6 oct sch
Municipality: Scon				:	
	10:X1452a35026	Maintainer Name ar	nd License No. Smil	lie's Sewer Service/L2	 !428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
<ul> <li>☐ Tank(s) Pumped</li> <li>☐ Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes ☐ No (if no provide measurements)</li> </ul>		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rei	move septage:   Maintena	nce Hole Hother (e	enter authorization c	ode)	
3. Is there evidence	of tank leakage from a sepaged, cracked, or structur	otic, holding, pretrally unsound main	tenance hole cove	ers? Yes HNo	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ► No	Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes No	☐ Yes ▼No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 <u>V∂</u> <b>5. Other information</b>	of septage were removed gal Tank #2 1000 a: List any troubleshooting e disposal:	gal Pretreatment, minor repairs con	nducted, tank safe	ety concerns, or othe	gal gal er concerns.
		Smilie's Sewer	Service		

PO BOX 100

Scandia, MN 55073

License# 2428 P: 651-433-3934