

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

<u>prior</u> to perfo	rming maintenance activition	es and remain on	-site for the duration	on or the maintenant	le activity.
Date of Maintenance:	6~3~7,4 Reason f	for Majntenance;/_	Kpg M	aint	7 B
Property Address: Z	415 Lisbon	Ave N F	Property Owner's Na	ame: Marvin Kl	pezke
Municipality: 4 Ke	Plno ZIP: 530	42 Property Idea	ntification Number:		
Maintenance Permit N	200 200	aintainer Name ar	nd License No. Smili	ie's Sewer Service/L24	128
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers se Is there evidence 	move septage: Maintenar ecurely replaced? Yes of tank leakage from a sep aged, cracked, or structura	□ No tic, holding, pret	reatment or pump	tank below the opera	ating depth or
evidence of dam	aged, Cracked, or structura	alty unsound mair	terrance note cove	ers? \(\text{Yes} \)	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_1500	gal Tank #2 1: List any troubleshooting, te disposal:	gal Pretreatmen			gal r concerns.
		C	C		

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073 License# 2428 P: 651-433-3934