

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 6/4/2024 Reason f	CENTRAL PROPERTY STATE OF THE PROPERTY OF THE	Recy	ion of the manter	narree derivity.
Property Address: 20545 July Av			ame: Lloyd 1	rad oon
Municipality: Forest cake ZIP: 550.				
Maintenance Permit No:56710 WS5387 M				/L2428
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
 Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater urements)			
 Access used to remove septage: Maintenant Were all covers securely replaced? Yes Is there evidence of tank leakage from a septage evidence of damaged, cracked, or structural 	□ No tic, holding, preto ally unsound main	eatment or pump tenance hole cove	tank below the opers? Yes No	F (FF)
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes ☐No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes No	☐ Yes No	Yes No	
4. How many gallons of septage were removed? Tank #1 000 gal Tank #2 5. Other information: List any troubleshooting, The C' part of the company of the co	gal Pretreatmen			gal gal other concerns.

Smilie's Sewer Service PO BOX 100

Scandia, MN 55073

License# 2428 P: 651-433-3934