Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 12818035505
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 6/11/24 Property ID #:
Property Address: 14363 Oren RD W Scandia MN 55073 Street Address City State Zip
Property Owner Name: Ann Rinkenberger
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: □Yes No Verification Method Used: Leaking Out: □Yes No Leaking In□Yes No Cover Damaged: □Yes No
Tank #2:□Yes □ No Verification Method Used: Gallons Removed: Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□No
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed:
Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location Other remarks or Concerns:
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.

