Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	Permit #: C6801M35506
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 6/11/24	Property ID #:
Property Address: 22780 Imperial Ave. Street Address	V Forest Lake MV 55826 City State Zip
Property Owner Name:	
Maintenance Performed	
☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Sludge-	and Scum Measured: (must be completed if tanks NOT pumped) Level of Tank:in Sludge Level:in evel:in FScum/Liquid Levelx100=%Sludge & Scum must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? ☐ Yes ☐ No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: ☐ Yes ☐ No Verification Method Used: Û'sual ☐ Gallons Removed: ☐ UDBO Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #2:□Yes No Verification Method Used: Usual Gallons Removed: 1000 Leaking Out:□Yes No Leaking In:□Yes No Cover Damaged:□Yes No	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Gallons Removed: Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes No Verification Method Used: ÛİSÜÜ Gallons Removed: 500 Leaking Out: ☐ Yes No Cover Damaged: ☐ Yes No Waste Disposal Method: ☐ Freatment plant ☐ Land Apply: Location Other remarks or Concerns: ☐	
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, Phone Number: 651-464-2082 License Number: I hereby certify as a State of Minnesota certified SSTS Maintainer supervised others in the performance of this job. Maintenance activities must be reported to the D	L216 that I personally conducted the work and made the observations, or directly

