Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informa	tion	Permit #:	4777	9135504	
Complete in its entirety to constitute a valid r maintenance activities and remain on-site for	naintenance perr	nit This permit must h	e complete		;
Date of Maintenance: 6/11/24	Pi	roperty ID #:			_
Property Address: 22760 Imperial Street Address	Hue F	Ovest Lake City	MN State	55025 Zip	
Property Owner Name: V					_
Maintenance Performed					
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☑ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level of Scum Level: Sludge+Scum/_ Tanks must be	Im Measured: (must be Tank:inininintiquid Level_Pumped if 25% or gre	n Sluc	lge Level:	in
Maintenance Informatio	n				
Access used to remove septage: Main			orization co	de)	
Were all covers securely replaced 🖫 Yes					
Is the tank designed as a leaky? Ex. Seep					_
Tank #1: ☐ Yes ☑ No Verification Method Used: Û See ☐ Gallons Removed: 1500					
Leaking Out: Yes No Leaking In Yes					
Tank #2:□Yes ★ No Verification Method			allons Rem	oved: 1000	
Leaking Out: ☐ Yes No Leaking In: ☐ Yes					7
Tank #3: ☐ Yes ☐ No Verification Method			allons Rem	oved:	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes					
Tank #4: ☐ Yes ☐ No Verification Method	V		illons Rem	oved:	
Leaking Out: Yes No Leaking In: Yes		1			1
Pump Tank: Yes No Verification Met			Gallons Rei	moved:_400	
Leaking Out: ☐ Yes No Leaking In: ☐ Yes Waste Disposal Method: ☐ Treatment pla					
Other remarks or Concerns:	nt 🗀 tand Appr	y: Location			
			-		
Maintainer Information				111	
Maintainer Name: Olson's Sewer Service In		Maintainer Signatu	ire:	475	E
Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216					
		annelle annele state date			
I hereby certify as a State of Minnesota certified SSTS supervised others in the performance of this job. Maintenance activities must be reported			cand made th	e observations, or directly	

