Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 18350 m 35362	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 1919124	
Property Address: Street Address	and Court North Forest Lake MN 55025
Property Owner Name: See Boettcher	
Maintenance Performe	ed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes □ No If No, Explain:	
Is the tank designed as a leaky? Ex. Se	repage pit, cesspool drywell leaching pit rood Used: Gallons Removed: //50
Tank #2:□Yes□ No Verification Meth	od Used: Gallons Removed: Yes □ No Cover Damaged:□Yes□No
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: Yes No Verification Method Used: Leaking Out: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns:	
	e Inc. Maintainer Signature:

Maintenance activities must be reported to the Department within 90 days.

