Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 123586x341900	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 4-29-2+ Property ID #:	
Property Address: 4850 (Street Address	CCMYCA Dr Cecelbury MM 551
Property Owner Name: Sean Figure	
Maintenance Perform	ed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scun Tanks must be Pumped if 25% or greater
Other: Maintenance Information Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? □ Yes □ No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit	
Tank #1:□Yes☑No Verification Met <u>Leaking Out:□Yes☑No Leaking In□</u> Yes□ No Verification Met	Gallons Removed: 1750 Ces □ No Cover Damaged: □ Yes □ No Gallons Removed: Gallons Removed:
Tank #3: \Box Verification Method Used: Gallons Removed: Leaking Out: \Box Verification Method Used: Gallons Removed: Tank #4: \Box Verification Method Used: Gallons Removed: Gallons Removed: Cover Damaged: \Box Verification Method Used: Gallons Removed:	
Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location	
Maintainer Informatio Maintainer Name: Pinky's Environmenta Maintainer Address: P.O. Box 354 Afton, Phone Number: 651-439-4847	N I Sewer Service Inc. Maintainer Signature

Washington County

Maintenance activities must be reported to the Department within 90 days.