Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 62229 A35515		
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: 6-25-24 Property ID #:		
Property Address: 22366 KIRK COURT N Scaudia State Zip		
Property Owner Name: Bryan 69 SSY		
Maintenance Performed		
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	OR	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/in x100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Informa	tion	
Access used to remove septage: Maintenance Hole Other (enter authorization code)		
Were all covers securely replaced? Yes□No If No, Explain:		
Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit		
Tank #1: ☐ Yes ☑ No Verification Method Used: Gallons Removed: Gallons Removed:		
Leaking Out: ☐ Yes No Leaking In ☐ Yes No Cover Damaged: ☐ Yes No		
Tank #2:□ Yes ☑ Verification Method Used: Gallons Removed: /oo/		
Leaking Out: ☐ Yes No Leaking In: ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No		
Tank #3:□Yes No Verification Method Used: Gallons Removed:		
Leaking Out: ☐ Yes ☐ Yes ☐ Yes ☐ Cover Damaged: ☐ Yes		
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed:		
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Pump Tank: Yes No Verification Method Used: Gallons Removed: Gallons R		
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location		
Other remarks or Concerns:		
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216		
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.		

