## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: H8090T.35516	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 6.35.24 Property ID #:	
Property Address: 1050 167H Street Address	ST Scawia MU 556873 City State Zip
Property Owner Name:	
Maintenance Performed	
Tanks Pumped:  Emergency Home Sale High-level alarm Routine/Maintenance Compliance Inspection Repair Other:  Maintenance Information	Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/in Sludge+Scum/Liquid Levelx100=%Sludge & Scun Tanks must be Pumped if 25% or greater
Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced: No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No  Tank #2: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Cover Damaged: Yes No	
Tank #3:□Yes □ No Verification Method Used: Gallons Removed:	
Leaking Out:   Yes   No   Cover Damaged:   Yes   No    Tank #4:   Yes   No   Verification Method Used:   Gallons Removed:    Leaking Out:   Yes   No   Cover Damaged:   Yes   No    Pump Tank:   Yes   No   Verification Method Used:   Gallons Removed:    Leaking Out:   Yes   No   Verification Method Used:   Gallons Removed:    Leaking Out:   Yes   No   Cover Damaged:   Yes   No    Waste Disposal Method:   Yes   No   Cover Damaged:   Yes   No    Other remarks or Concerns:   Other remarks or Concerns:   Yes   No   Yes   No    Other remarks or Concerns:   Yes   No   Yes   No   Yes   No    Other remarks or Concerns:   Yes   Yes	
Maintainer Information Maintainer Name: Olson's Sewer Service Ir Maintainer Address: 17638 Lyons St. NE For Phone Number: 651-464-2082 License	est Lake, MN 55025  Number: L216  Maintainer that I personally conducted the work and made the observations, or directly

