## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	etion Permit #: £1746034950
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 4-24-24 Property ID #:	
	e ave n Stillwater MN 55082 City State Zip
Property Owner Name: Linda Rivard	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scur  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit	
Tank #1:□Yes ☑No Verification Method Used: Gallons Removed: Leaking Out:□Yes☑No Leaking In□Yes☑No Cover Damaged:□Yes☑No	
Tank #2:□Yes□ No Verification Method Used: Gallons Removed: Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□No	
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #4: ☐Yes ☐ No Verification Method	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank:   Yes No Verification Method Used:  Leaking Out:   Yes No Cover Damaged:   Yes No  Waste Disposal Method:   Treatment plant   Land Apply: Location   Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Pinky's Environmental Sewer Service Inc.  Maintainer Address: P.O. Box 354 Afton, MN 55001  Phone Number: 651-439-4847  License Number: L1673  I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.  Maintenance activities must be reported to the Department within 90 days.	