Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informati	10n Permit #: 96039 934952
than of detivities and remain on-site for the	intenance permit. This permit must be completed prior to performing ne duration of the maintenance activity.
Date of Maintenance: 4-23-24	Property ID #:
Property Address: <u>8250</u> Lake Electric Street Address	City State Zip
Property Owner Name: Rob Dengle	r
Maintenance Performed	
☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Yes ☐ Is the tank designed as a leaky? Ex. Seepage Tank #1: ☐ Yes ☐ No Verification Method Use	nance Hole Other (enter authorization code) No If No, Explain: P.A.s e pit, cesspool drywell leaching pit sed: Gallons Removed: / Z 56
Leaking Out: ☐ Yes☑No Leaking In ☐ Yes☑ I Tank #2: ☐ Yes☑ No Verification Method Us Leaking Out: ☐ Yes☑No Leaking In: ☐ Yes ☐	No Cover Damaged: ☐ Yes ☐ No sed: Gallons Removed: / Z S \\ Section =
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Tank #4: ☐ Yes ☐ No Verification Method Us	No Cover Damaged: ☐ Yes ☐ No
Leaking Out: ☐ Yes ☐ No Verification Method Os Pump Tank: ☐ Yes 점 No Verification Method	No Cover Damaged: ☐ Yes ☐ No
Leaking Out: ☐ Yes☑ No Leaking In: ☐ Yes☑ Waste Disposal Method: ☐ Treatment plant Other remarks or Concerns:	No Cover Damaged: ☐ Yes ☐ No
Maintainer Information Maintainer Name: Pinky's Environmental Sewe Maintainer Address: P.O. Box 354 Afton, MN 5 Phone Number: 651-439-4847	5001 License Number: L1673 intainer that I personally conducted the work and made the observations, or directly

Washington County