Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	Permit #: <u>M5393a 34802</u>
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 4-19-24	Property ID #:
Property Address: 8719 Oakgreen Ave Street Address	S Hastings MN 55033 City State Zip
Property Owner Name: Mike Chamberlain	
Maintenance Performed	
☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Page 15	ge and Scum Measured: (must be completed if tanks NOT pumped) d Level of Tank:in Sludge Level:in Level:in ge+Scum/Liquid Levelx100=%Sludge & Scum
□ Other: Maintenance Information	s must be Pumped if 25% or greater
Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Wes No	
Tank #4: ☐ Yes ☐ No Verification Method Used:_	Gallons Removed:
Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Visual Gallons Removed: Leaking Out: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns: Monhole under duck. Cannot expose	
Maintainer Information Maintainer Name: Pinky's Environmental Sewer Service Inc. Maintainer Address: P.O. Box 354 Afton, MN 55001 Phone Number: 651-439-4847 License Number: L1673 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.	

Washington County