

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perfor	ming majntenance activiti	es and remain on	site for the durat	ion of the maintena	nce activity.
Date of Maintenance: 5/2/16 Reason for Maintenance: ROUTINE					
Property Address: 7903 1/3+4 ST. S. Property Owner's Name: JOHN SWENSON					
Municipality: CoTAC	E GROVE ZIP: 550)/6 Property Ide	ntification Number	:	
	:X6838y0598N			A	715
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⋈No	☐ Yes ☒No	☐ Yes ☒No	
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes No	☐ Yes 🕅 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1000	gal Tank #2 <u>1000</u>	gal Pretreatmen	tankg	al Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.