## **Subsurface Sewage Treatment System Maintenance Permit**

<b>Property/Owner Informat</b>	ion Permit #: 95615e 35524
Complete in its entirety to constitute a valid ma maintenance activities and remain on-site for the	intenance permit. This permit must be completed prior to performing
Date of Maintenance: 7/2/24	Property ID #:
Property Address: 23770 Inwood F Street Address	City State Zip
Property Owner Name: Dean Speidel	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scur  Tanks must be Pumped if 25% or greater
Maintenance Information	
	enance Hole Other (enter authorization code)
Were all covers securely replaced?☆Yes□	No If No, Explain:
Is the tank designed as a leaky? Ex. Seepag	
Tank #1: ☐Yes No Verification Method U	Ised: U`Sucr Gallons Removed: 1630
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐	No Cover Damaged:□YesᡌNo
	lsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	- Po
	lsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
	sed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Pump Tank: ☐ Yes ☐ No Verification Metho	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Waste Disposal Method: ☐Treatment plant ☐ Land Apply: Location	
Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc.  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082  License Number: L216	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

