

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	4629 Wild Canyon Trail, W		* 5	***************************************		
	t No:					
Mainte	nance Performed		*	completed if tanks	NOT pumped)	
☑ Tank(s) Pumped		23 41	Tank in	Scum Level in Tank	in	
☐ Sludge and scum measured						
Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		= % Sludge & Sci	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
			enter authorization co			
	securely replaced?			tank below the opeers? No-couldn't	erating depth or conf <u>irm precast via</u>	
					erating depth or conf <u>irm precast via</u>	
	te of tank leakage from a se maged, cracked, or structu	Leaking Out	reatment or pump Itenance hole cove	camera	erating depth or confirm precast via	
	te of tank leakage from a se maged, cracked, or structu Tank	Leaking Out Yes No Some answers un	reatment or pump Itenance hole cove	Cover Damage Yes No Dugh inspection pipe.	erating depth or confirm precast via	
	Tank Septic/Holding Tank #1	Leaking Out Yes No Some answers un	reatment or pump tenance hole cove Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dugh inspection pipe.	erating depth or confirm precast via	
	Tank Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No known. Pumped thro	Cover Damage Yes No Dugh inspection pipe. Yes No	erating depth or conf <u>irm precast via</u>	
3. Is there evidence evidence of da	Tank Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No	Leaking In Yes No No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No	erating depth or confirm precast via	
4. How many gallo Tank #1 1200	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Pump Tank puss of septage were removed gal Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No No Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Pes No	gal	
4. How many gallo Tank #1 1200	Tank Septic/Holding Tank #2 Pretreatment Tank Pump Tank Pums of septage were remove	Leaking Out Yes No Yes No	Leaking In Yes No No Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Dugh inspection pipe. Yes No Yes No Yes No Pes No	gal	

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033 License# 2989 P: 651-459-3718

Maintenance activities must be reported to the Department within 90 days.