

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	permit. This permit	must be completed
<u>prior</u> to perfo	rming maintenance activit	ies and remain on	-site for the dura	tion of the maintena	nce activity.
	X/X//6 Reason				
Property Address: _/c	0150 KIMBRO	CIRCLES	Property Owner's N	Name: DARIN	HUSABY
Municipality: <u>COTTA</u>	GE GROVE ZIP: 550	Property Ide	ntification Number	r:	
Maintenance Permit N	10: <u>y 0429a0588</u> M	Maintainer Name a	nd License No	MEYER-L9	15
Maintena	nce Performed	Tank Meas	surement (must be	e completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers se</li><li>3. Is there evidence</li></ul>	nove septage: Maintenal curely replaced? Yes of tank leakage from a sep aged, cracked, or structure	□ No tic, holding, preti	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ⊠No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🗵 No	☐ Yes 🗷 No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1205 gal Tank #2		gal Pretreatmen	t tankg	gal Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.