Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	tion Permit #: 16898 x 36237
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7/9/24	Property ID #:
Property Address: 11805 Mayberry Street Address	Tr/ N Marine MN 55047 City State Zip
Property Owner Name:	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced? A Yes[Is the tank designed as a leaky? Ex. Seepa	tenance Hole Other (enter authorization code) No If No, Explain:
Leaking Out: ☐ Yes No Leaking In ☐ Yes	TNo Cover Damaged:□Yes社No Used: Uisual Gallons Removed: 1000
	Used: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	□ No Cover Damaged: □ Yes □ No
Pump Tank: ☐ Yes INo Verification Meth Leaking Out: ☐ Yes INO Leaking In: ☐ Yes Waste Disposal Method: ☐ Treatment plan Other remarks or Concerns:	No Cover Damaged: ☐ Yest No



Maintenance activities must be reported to the Department within 90 days.