Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: x8831x36238	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
	Property ID #:
Property Address: 23245 \$ tasca Street Address	AUL City State Zip
Property Address: 23245 \$ tasca Ave N Street Address City State Zip Property Owner Name: Sand Chatwin	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Were all covers securely replaced? Yes Is the tank designed as a leaky? Ex. Seepag	enance Hole Other (enter authorization code) No If No, Explain:
Leaking Out:☐Yes☐Mo Leaking In☐Yes☑	No Cover Damaged: Yes Solo Sed: Gallons Removed: /000
Tank #3:□Yes☑No Verification Method U Leaking Out:□Yes☑No Leaking In:□Yes ☑ Tank #4:□Yes□No Verification Method U	Sed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Pump Tank: ☐ Yes ☐ No Verification Metho	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method: ☑ Treatment plant Other remarks or Concerns:	No Cover Damaged:□Yes□No □ Land Apply: Location
	umber: L216 sintainer that I personally conducted the work and made the observations, or directly

