

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit r	nust be completed	
<u>prior</u> to perfor	ming maintenance activi	ties and remain on	-site for the durat	ion of the maintenar	nce activity.	
Date of Maintenance:	5/9/16 Reason	for Maintenance:	ROUTINE			
Property Address:	3630 12th S	T. N.	Property Owner's N	ame: TERRY 7	OMPKINS	
Municipality: LAKE	ELMO ZIP: 550	Property Ide	ntification Number	:	-	
Maintenance Permit N	o: <u>r3213206/1</u>	Maintainer Name ar	nd License No. <u>M</u>	EYER - L	915	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Sco	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? 🕅 Yes of tank leakage from a se aged, cracked, or structur	ptic, holding, preti			rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🛚 No	□ Yes 🏿 No	☐ Yes 🂢 No		
	Septic/Holding Tank #2	☐ Yes 💆 No	☐ Yes 🏚 No	☐ Yes 🎗 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 1600 gal Tank #2 1600		_ gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or other	er concerns.	