Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 29166n 3624/
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 7/12/24 Property ID #:
Property Address: 9255 96th St. N. Mahtomesi 55115 Street Address City State Zip Property Owner Name: 247 Sharmon Bes Car
Property Owner Name: Pats Sharmon Beskar
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information
Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used: Gallons Removed:/
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature: Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Washington County

Maintenance activities must be reported to the Department within 90 days.