

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety	to constitute a vai	id maintenance pe	ermit. This permit n	ilust be completed	
prior to perfor	ming maintenance activi	ties and remain on	site for the durati	on of the maintenar	nce activity.	
Date of Maintenance:	5/16/16 Reason	for Maintenance:	Routin		$\mathcal{Q}$	
Property Address:&	39th S	t. 91. P	roperty Owner's Na	ame: <u>Dennis</u>	Bernslett	
Municipality:	be Elmo ZIP: 55	Off Property Ider	ntification Number:			
-	o:069800632				5	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
₹ Tank(s) Pumped		11	Liquid Level of Tank in			
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers se 3. Is there evidence	nove septage: Maintena curely replaced? Wes of tank leakage from a se aged, cracked, or structu	□ No ptic, holding, pretr	eatment or pump	tank below the ope	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🏹 No	☐ Yes 🗷 No	☐ Yes 📉 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	$\square$ Yes $\square$ No	☐ Yes ☐ No		
	Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No		
4. How many gallons	Pump Tank  of septage were remove	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1200	Pump Tank	☐ Yes ☐ No  d?  gal Pretreatmen	☐ Yes ☐ No t tankg	☐ Yes ☐ No al Pump Tank	gal	