Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: C (0350 \rm 310250)	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7-22-24 Property ID #:	
Property Address: 9914 Meh Shake trail forest take MN 55025 Street Address City State Zip	
Property Owner Name:	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location Other remarks or Concerns:	
	st Lake, MN 55025 Number: L216 aintainer that I personally conducted the work and made the observations, or directly

Washington County