## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information

maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 7.23-24	Property ID #:
Property Address: 20486 Hols	tad Wail freather MN 55025
Property Owner Name: Randy Komstra	
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scum  Tanks must be Pumped if 25% or greater
Maintenance Information  Access used to remove septage: Maintenance Hole Other (enter authorization code)  Were all covers securely replaced? Mo If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1	
Tank #2:	
Leaking Out: Yes No Cover Damaged: Yes No   Pump Tank: Yes No No Verification Method Used: Gallons Removed: Leaking Out: Yes No   Leaking Out: Yes No Cover Damaged: Yes No   Waste Disposal Method: Treatment plant Land Apply: Location   Other remarks or Concerns:	
Maintainer Information  Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature:  Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025  Phone Number: 651-464-2082 License Number: L216  I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.  Maintenance activities must be reported to the Department within 90 days.	

